Appl. No.: 10/557,538

Amdt. dated October 11, 2010

Reply to Office Action of June 11, 2010

Amendments to the Specification:

Please amend page 5, line 14 of the Specification as indicated below: "the accelerometer 2. In the event of the piston 57 suffer suffering an impact at the end"

Please amend page 6, line 22 of the Specification as indicated below: "support 3, one positions the [a] first insulating element 20' and, on top of it, the"

Please amend page 6, line 24 of the Specification as indicated below: "configure the accelerometer 2 and have the signal terminal 33 an and the feed"